

Republic of the Philippines  
GUIMBA WATER DISTRICT  
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT  
SEPTEMBER 16-30, 2021

SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
BACAYAO BOOSTER PUMPING STATION	0.33 9:21AM																3
BACAYAO PUMPING STATION		0.32 9:17AM															1
BALINGOG WEST			0.29 8:56AM														4
STA. CRUZ				0.28 8:00AM													4
SAN ANDRES PUMPING STATION					0.33 7:30AM												1
BALBALINO						0.25 7:57AM											4
LENNEC							0.28 8:04AM										4
SAN RAFAEL PUMPING STATION								0.33 9:17AM									1
SAN BERNARDINO									0.27 9:50AM								4
CABARUAN										0.29 10:40AM							4
GUISET											0.30 7:48AM						4
TAMPAC 2-3 PUMPING STATION												0.33 9:40AM					1
CAWAYANG BUGTONG													0.27 7:54AM				4
CULONG														0.28 8:00AM			4
RUFINA HOMES V PUMPING STATION															0.3 7:20AM		1

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap  
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

  
FRANCIS E. ESQUIVEL  
DIVISION MANAGER B-ENGINEERING

  
RAUDERICK A. RAMOS  
SR. WATER MAINTENANCE MAN-A

  
ROMMEL G. GRAGASIN  
DIVISION MANAGER B-PRODUCTION

  
ENGR. FELIXBERTO C. LEGARDA  
GENERAL MANAGER

Republic of the Philippines  
GUIMBA WATER DISTRICT  
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT  
SEPTEMBER 1-15, 2021

SAMPLING LOCATION	DAYS OF THE MONTH ( Residual =PPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
PARTIDA 1	0.27 8:28AM															4
STA. VERONICA PUMPING STATION		0.32 7:07AM														1
AGCANO			0.25 8:28AM													4
SINULATAN				0.27 11:40 AM												4
SAN ROQUE PUMPING STATION					0.32 8:18AM											1
LAMORITO						0.24 8:17AM										4
MACATCATUIT							0.29 8:30AM									4
BANTUG PUMPING STATION								0.33 9:19AM								1
NAGLABRAHAN									0.24 10:36AM							4
MACAPABELLAG										0.27 7:44AM						4
BAGONG BARRIO											0.28 8:22AM					4
MATURANOC PUMPING STATION												0.33 10:16AM				1
NAGPANDAYAN													0.27 8:42AM			4
BUNOL														0.28 8:00AM		4
SAN MARCELINO															0.28 8:03AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap  
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

  
FRANCIS E. ESQUIVEL  
DIVISION MANAGER B-ENGINEERING

  
RAUDERICK A. RAMOS  
SR. WATER MAINTENANCE MAN-A

  
ROMMEL G. GRAGASIN  
DIVISION MANAGER B-PRODUCTION

  
ENGR. FELIXBERTO C. LEGARDA  
GENERAL MANAGER